



[Knowledge Base Home](#)

- [KIS001364 - Answering and disconnecting a VoIP call from a Bluetooth headset](#)
- [KIS001321 - Creation of SIP & VoIP profiles with LCP plug-in fails](#)
- [TSS000776 - Payload conversion for G.729 audio format](#)
- [TSS000713 - Creating video and VoIP calls](#)
- [TSS000709 - Managing VoIP profiles](#)
- [TSS000650 - Increasing WLAN power efficiency for full-duplex VoIP and Video applications](#)
- [KIS001078 - Updating to VoIP Client Provisioning plug-in Rel 2 fails](#)
- [KIS000921 - Retrieving VoIP status information not possible with public APIs](#)
- [KIS000796 - Frame length variation for G.711 encoder](#)
- [KIS000356 - Large amount of Phonebook entries causes performance problems with VoIP calls](#)
- [KIS000347 - Audio routing limitations on S60 3rd Edition](#)