



<b>ID</b>	KIS000354	<b>Creation date</b>	July 7, 2006
<b>Platform</b>	S60 3rd Edition	<b>Devices</b>	Nokia E61 (sw 1.0610.04.04)
<b>Category</b>		<b>Subcategory</b>	

**Keywords (APIs, classes, methods, functions):**

## Overview

Copy-pasting text into an editable text field causes a panic.

## Description

This known issue affects Nokia E61 with software version 1.0610.04.04.

Some 3rd-party applications may exit with WSERV 66 panic code when copying text to clipboard and trying to paste (Ctrl+V) it into an editable text field. This happens when the application does not have the SwEvent capability.

## How to reproduce

(See detailed description).

## Solution

Applications running on the Nokia E61 with software version 1.0610.04.04 require SwEvent capability to avoid WSERV 66 panic when pressing Ctrl+V (Paste) in editable text fields. This issue is fixed in later software versions.